
Release Addendum

Courier Analog V.90 Release V 1.0

What is new in this release?

These new features are included in this release. For more information about these features, refer to the documentation provided with the product.

- V.90

Compatibility information

This software can be run on all V.34 or higher Courier V. Everything internal and external Modems.

Other important notes about compatibility

Free upgrades are available to all current x2 customers. Those customers who do not have x2 technology will require at least an V.90 enable key to achieve V.90. If the modem is not at least V.34 a hardware upgrade is required. For more information about V.90 upgrades see the TOTALservice Online web site at <http://totalservice.usr.com> or call 1-888 I WANT 56.

Issue Resolutions for V 1.0

Resolved issues for this product are listed here.

- Problems achieving X2 connections on certain phone lines.
- Courier modem can not do 14.4 faxing with +FBO=1 at speeds other than 9600 or 2400

V.90 Troubleshooting

- The ITU V.90 protocol, has impacted the operation of the V.8 protocol. In most instances you will not encounter any problems connecting to older non-U.S. Robotics equipment. However, you may encounter problems when connecting to equipment that implements the V.8 protocol incorrectly. To resolve this problem, disable V.90 by issuing the ATS58=32 command to the modem.
- In this release of the V.90 code status messages for ATI11V.90 are not present on failed X2/v.90 calls. This will be re-implemented in future releases of this firmware.